

SECTION VI - REACTIVITY and STABILITY DATA

STABILITY	Unstable		Conditions to avoid
	Stable	X	Heat and open flame.

INCOMPATIBILITY(Materials to Avoid) Strong oxidizers and alkalies.

HAZARDOUS DECOMPOSITION or BY PRODUCTS Hydrogen chloride, carbon monoxide, carbon dioxide, traces of phosgene and chlorine.

HAZARDOUS POLYMERIZATION	May Occur		Conditions to avoid
	Will not Occur	X	None known.

SECTION VII - HEALTH HAZARD DATA

Routes of entry	Inhalation? X Yes	Skin? X Yes	Ingestion? X Yes	Eyes? X Yes
-----------------	-------------------	-------------	------------------	-------------

Health Hazards	Acute		
	Chronic	X	Chronic over-exposure could result in liver disease and rhythm disorders of the heart.

Carcinogenicity:	NTP?	IARC Monographs?	OSHA Regulated?
------------------	------	------------------	-----------------

Not a carcinogen according to OSHA/NTP/IARC.

Signs and Symptoms of Exposure None

Medical Conditions Generally Aggravated by Exposure

None

Emergency and First Aid Procedures

Eyes: Immediately flush with large amts. of water for 15 minutes holding eyelids open. Skin: Remove contaminated clothing and wash skin with water. Inhalation: Move to fresh air. Ingestion: Immediately contact physician or Local Poison Control Center.

SECTION VIII - PRECAUTIONS FOR SAFE HANDLING and USE

Steps to be Taken in Case Material is Released or Spilled Wear personal protective equipment. Remove heat and ignition sources; ventilate the area; clean with inert absorbant.

Waste Disposal Method May be burned in an approved incinerator or dispose of according to all Local, State and Federal regulations.

Precautions to be Taken in Handling & Storage Store in closed container in cool, well-ventilated area.

Other Precautions Note to Physician: Do not give epinephrine-type drugs.

SECTION IX - CONTROL MEASURES

Respiratory Protection (Specify Type) If TLV is exceeded or for symptoms of over-exposure, wear NIOSH approved respirator for Local Exhaust organic vapors to maintain exposure levels below 350 PPM.

Ventilation	Local Exhaust	Special	None
	Mechanical (General)	Other	None

Eye Protection Safety glasses Other Protective Clothing or Equipment None

Work/Hygienic Practices Avoid skin contact & breathing vapors. Wash hands prior to eating,

SECTION X - TRANSPORTATION INFORMATION (optional)

D.O.T. Proper Shipping Name 1,1,1-Trichloroethane D.O.T. Hazard Class ORM-A

If a "Consumer Commodity ORM-D" What is the qualifying Chemical? or ORM-A 1,1,1, Trichloroethane

D.O.T. I.D. NO. (UN or NA) UN 2831 Hazard Label or Marking Required on Shipper Ctn. None

IATA Proper Shipping Name 1,1,1- Trichloroethane IATA Hazard Class ORM-A IMO NO. 6.1